

EAST Search History**EAST Search History (Prior Art)**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	10	"4188821"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 12:50
L2	5	1 and (radial\$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 12:55
L3	128	(frank near3 michel).in.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:00
L4	165	"wittenstein ag"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:01
L5	6	3 and (load strain stress pressure force) near3 (sens\$4 measur \$4 transducer detect \$4 gage gauge)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:02
L6	5	5 and (shaft driveshaft)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:02
L7	7	4 and (load strain stress pressure force) near3 (sens\$4 measur \$4 transducer detect \$4 gage gauge)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:03

L8	357669	transmission.clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:04
L9	157	8 and (radial\$4) near3 (load strain stress pressure force) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:04
L10	5	3 and (temperature incremental) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:05
L11	3	4 and (temperature incremental) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:05
L12	9	8 and (pair couple array plural\$4 two second multiple) near3 (temperature incremental load strain stress pressure force) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge) near3 (radial \$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:06
L13	313	(pair couple array plural\$4 two second multiple) near3 (temperature incremental load strain stress pressure force) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge) near3 (radial \$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:11
L14	89	13 and (shaft)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:11

L15	56	14 and (housing casing frame)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:12
L16	40	15 and (transmission motor)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:12
L17	546838	(transmission).ti.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:15
L18	17	17 and (temperature incremental load strain stress pressure force) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge) near3 (radial \$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:15
L19	1	18 and (flange)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:16
L20	7	18 and (shaft)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:16
L21	13374	driveshaft	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:18
L22	2883	21 and (output) near3 (shaft)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:18

L23	837	22 and (flange)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:18
L24	0	23 and (temperature incremental load strain stress pressure force) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge) near3 (radial \$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:18
L25	161	23 and (temperature incremental load strain stress pressure force) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:18
L26	53	25 and (circumferential \$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/11/12 13:19

EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L27	219304	transmission.clm.	USPAT; UPAD	OR	ON	2009/11/12 13:26
L28	4762	27 and (flange).clm.	USPAT; UPAD	OR	ON	2009/11/12 13:26
L29	2111	28 and (shaft).clm.	USPAT; UPAD	OR	ON	2009/11/12 13:26
L30	0	29 and (temperature incremental load strain stress pressure force) near3 (sens\$4 measur\$4 transducer detect\$4 gage gauge) near3 (radial \$4).clm.	USPAT; UPAD	OR	ON	2009/11/12 13:26

L31	56	29 and (temperature incremental load strain stress pressure force) near3 (sens\$4 measur\$4 transducer detect\$4 gage gage).clm.	USPAT; UPAD	OR	ON	2009/11/12 13:26
L32	18	31 and (radial\$4). clm.	USPAT; UPAD	OR	ON	2009/11/12 13:27

11/12/09 1:34:19 PM